

## Programming Tips

---

If you are programming in VB 6, you can use and modify the full source code for the ISO-14230 USB Message Center which is on the Installation CD in the Reference Software folder.

There is also a VB .NET 2005 project full source code that can be used as a starting point as well, in the Reference Software folder on the CD.

There are also header files for C and VB in the Reference Software folder on the CD.

Latest software Versions as of August 3, 2018

---

Latest 14230USB.DLL version is 2.0.0.9.  
Latest driver and message center install package is 1.0.18.  
Latest firmware revision is 50.5.

New Drivers in Install Packages 1.0.18

---

The latest Windows 10 updates require a driver update. Please make sure to install the latest driver package if you are using Windows 10. The latest driver package is automatically installed if you install the Message Center or the driver package 1.0.18.

If you are using a 32-bit computer or Windows XP, you may find that the latest driver package won't install on your machine (fails to verify the signature). In that case, install an earlier version of the driver, such as 1.0.17 Message Center or driver package, which is located in the "Older Versions" folder.

Make sure to execute the x64 program if you have a 64-bit computer or the x32 program if you have a 32-bit computer.

New in version 2.0.0.9 of 14230 USB DLL

---

Fixed issue exiting application when no device connected.

Uses driver compatible with Windows 8 and Windows 10.

Please note that the new driver package is signed with a Digicert SHA2 EV certificate.

Native Windows 7 does not support SHA2 certificates. You will need to install the following Windows Update:

<https://support.microsoft.com/en-us/kb/3033929>

Windows 8 and newer have native support for SHA2 certificates.

Windows XP requires Service Pack 3 for SHA2 support.

Warning: with this driver, if you try to install with a 14230USB device plugged in, the driver installation will fail. Then you will have to unplug the 14230USB device, uninstall both the windrvr6 based driver and the current driver, and reinstall the drivers, and then plug in the device(s) again. See the README file in the driver folder for instructions about individual driver installation steps.

#### Problems With Certain Anti-Virus Software

---

Certain Anti-Virus software may prevent this software from loading or installing. For example, Avast on Windows 10 will prevent the installation from completing. It may be necessary to disable your anti-virus software, such as Avast, during the installation or first-time running of this software. The root cause of this is usually because the anti-virus software is unfamiliar with this software (or any software from small companies) and utilizes a heuristic based on the philosophy that "little is known about this software" to block it. Norton Sonar will also sometimes remove the 14230 USB Message Center. You will need to go into Norton and restore this application to use it.

#### Pure 64-Bit DLL Deprecated

---

Going forward, Silicon Engines will no longer support the pure 64-bit DLL. If you are using this, then please contact Silicon Engines and we will decide what to do. Normally, the 32-bit DLL works both in 32-bit and 64-bit Windows operating environments so a pure 64-bit DLL should not be necessary.

#### Model 9009 No Longer Supported

---

If you are using Model 9009 and everything is working, you can keep on using it as long as your Windows system allows. If your Windows system updates and the drivers no longer work for the Model 9009, you are encouraged to upgrade your Model 9009 to the Model 9010. The Model 9010 features improved speed and compatibility with Windows 8 and Windows 10. The interface to the Model 9009 and the Model 9010 is the same so any program that uses the Model 9009 will also be able to use the Model 9010. Contact Silicon Engines at [sales@siliconengines.net](mailto:sales@siliconengines.net) about upgrading your Model 9009 to Model 9010.

#### Error 1152 During Installation

---

If you get error 1152 during installation, then take

the following steps:

1. Disable all network adapters on your computer such that you no longer have an Internet connection.
2. Reboot your computer with network adapter disabled and try the installation. If you still get error 1152, then proceed to step 3.
3. If the installation still doesn't work, disable anti-virus software, reboot, and run the installation.

Note: make sure to re-enable anti-virus software and your network adapters after the installation has succeeded.

New in 1.0.11 Version of ISO-14230 USB Message Center

-----  
Support for up to 250,000 bps with version 1.5 of firmware. (Firmware can always be upgraded - it is on the CD and you can upgrade with this program). Previous maximum baud rate was 115,200 bps.

New in 50.5 Version of Firmware for Model 9010

-----  
Able to support baud rates up to 250,000 bps. Can be used to talk on a DMX system but requires special cabling and connection with custom modified 9001 box and USB-to-RS485 converter. Consult Silicon Engines at sales@siliconengines.net if you are interested in this type of development.

New in version 1.0.10 of ISO-14230 USB Message Center

-----  
Minor fixes: remove extra slash in filenames, don't display "Received 256 bytes order" if test mode is not enabled.

New in version 2.0.0.8 of 14230 USB DLL

-----  
Bug fix to ensure that all messages are received in proper order especially in the case of high bus utilization (theoretical bug fix - no actual issue was ever observed), other minor bug fixes to remove deadlocks and other types of mis-communication issues.

New in version 1.0.9 of ISO-14230 USB Message Center

-----  
Support for version 4 of Model 9010 firmware.  
If slow init alternate method is selected, then system ID will also be reported during request last keyword.  
Extra resistor modes are added to drop-down box for Voltage Selection.  
Baud rate box now takes baud rates up to 115200.  
New high speed duplex mode check box on config screen.  
Fix bug: voltage mode was not being saved on exit

from program.

Fix bug: voltage mode wasn't being sent properly in previous versions of message center program.

Fix bug: source and target addresses were reversed in previous incarnation of program when using fast init.

New in version 2.0.0.7 of 14230 USB DLL

-----  
Support for version 4 Model 9010 firmware (see below).

Note that starting with this version, the source address and target address arguments to the fast init routine only are reversed. This is fully backward compatible with earlier versions of applications because if the source address is entered as the target address (first argument) it now becomes the source address (first argument) and the code will behave the same.

The following routines were added (model 9010 support only):

    Iso14230USBExtendedOpen  
    Iso14230USBSetHighSpeedBaudRate  
    Iso14230USBSetBusCharacteristics  
    bit 2: 1=listener only 0=normal bit 3: 1=5V mode only

0=normal

    Iso14230USBSetHighSpeedDuplex  
    Iso14230USBExtendedSlowInit  
    Iso14230USBGetMostRecentSystemID

New in version 4 of Model 9010 firmware

-----  
Support for baud rates up to 115,200 bps.

New high speed duplex command for baud rates over 10,417 which allows all data transmitted to be echoed back if rendered on bus properly. This allows guaranteed delivery methods by checking the receive data and comparing with the data that was sent by the application program. This is not required for baud rates 10,417 or lower because for those baud rates, bit assertions are automatically checked and error codes generated if the bit assertions fail.

New alternate slow init command with system ID request.

This is the same as in version 20 of the ISO-14230 RS232 converter.

New settings which allow either forced 5V mode or forced no bus resistance mode (pure listener).

Bug fix: when receiving data and status responses simultaneously, some data would get dropped. This has been fixed.

New in Version 2.0.0.6 of 14230 USB DLL (Release 1.0.14)

-----  
Fixed a bug in the lumping together of receive data into packets: occasionally would not lump together properly. This has been fixed.

Greatly increased transmit speed, especially for

Windows 7, by changing the default size of the transmit queue from 4 to 8192.

Fixed a bug where an application written like the example code provided would be slow to respond to the mouse and keyboard even when the system was completely idle: now the system is slow to respond to the mouse and keyboard only when there is active bus activity and bytes being read (since the Iso14230USBReadDataMessage routine blocks for about half a second when called if there is any receive data being received for lumping purposes). Fixed a bug in custom tester present messages handling.

#### New in version 21 of USB firmware

-----

Note: if you are using Windows XP, it is recommended to use version 11 instead of version 21 since version 11 is faster. Version 21 fixed a bug in setting custom tester present messages that was data-dependent.

#### New in version 11 of USB firmware

-----

Note: version 11 of USB firmware is not compatible with Windows Vista, Windows 7, and Lenovo laptops with i3/i5/i7 cores. Version 11 fixed a bug in custom tester present message handling (which was data dependent).

#### New in Version 1.0.8 of 14230 USB Message Center

-----

Version 1.0.8 of the 64-bit executable corrects an issue with reprogramming of the converter box. The progress bar is not a registered class in 64-bit so the progress bar was removed for 64-bit. Version 1.0.8 of the .NET projects includes corrected pointer pinning techniques to fix bugs that appear mostly in the 64-bit environment.

#### New in Version 2.0.0.4 and 2.0.0.5 of 14230 USB DLL

-----

A bug fix to allow newly attached devices to be recognized without having to restart the message center. 2.0.0.5 of the DLL also includes better read data message support lumping together data in same packets better.

#### New in Version 2.0.0.3 of 14230 USB DLL

-----

Corrects a time-limit issue in version 2.0.0.2. If you have version 2.0.0.2 of the 14230 USB DLL, then you must upgrade to 2.0.0.3 or later.

#### Version 20 of USB Module

-----

This version should be used for computers with USB co-processors or Windows Vista or Windows 7. This version is slower than the regular version

(version 10, version 8, or version 7) but is compatible with those later systems. It requires special drivers. See also the file IncompatibilityI3I5I7VistaWindows7.TXT for more details on how to implement this version. It should not be used unless you need to use the box on one of those systems because it slows down the performance slightly.

New VB.NET 2005 Reference Source Code 1.0.6

-----  
This includes the necessary improvement to pin pointers used in calls to 14230USB.DLL in a managed environment (using .NET Framework).

New in Version 1.0.7 of 14230 USB Message Center

-----  
The message center has not changed but the main driver DLL, 14230USB.DLL, has changed. This also affects the Standalone Driver Install. The new DLL (dated 4/27/10) fixes issues in the last DLL which was supposed to be much faster but the old DLL actually had some issues which could cause the box to stop transmitting after continuous transmission and could also cause certain transmitted messages to become lost.

Version 10 of USB Module

-----  
Version 10 of the USB module is used for Serial Numbers 2000 and after. It is slightly superior, for factory purposes, than version 8. If you have version 8 already loaded, there is no reason to load version 10.

Version 8 of USB Module

-----  
Version 8 of the USB module is used for Serial Numbers 2000 and after. It adds support for USB suspend mode.

Version 7 of USB Module

-----  
Version 7 of the USB module is used for Serial Numbers before 2000. It adds support for USB suspend mode.

Version 6 of USB Module

-----  
Version 6 of the USB module is used for Serial Numbers 2000 and later. It is necessary for factory programming to use version 6 rather than version 5 for the newer modules.

New in Version 1.0.6 of 14230 USB Message Center

-----  
The message center has not changed but the main driver DLL, 14230USB.DLL, has changed. This also affects the Standalone Driver Install. The new DLL is much faster with respect

to turn around time on transmitting and receiving 14230 messages.

#### Upgrading Firmware

-----

The version of the 14230 USB converter is made of a major version and a minor version. The major version corresponds to the version of the USB firmware and the minor version corresponds to the version of the 14230 module firmware.

The firmware is upgradable through the 14230 USB Message Center. If you have a version earlier than 5.8, then you need to send your module back to Silicon Engines to perform the further upgrade. After version 5.8 all upgrades can be performed through the 14230 USB Message Center. Click on the Configure button and then the Upgrade Firmware button. Then choose the module you want to reprogram and then for the S19 file, browse to the Upgrade folder on the Installation CD and choose the appropriate file.

In version 5.4, the interprocessor communication bus speed was lowered due to occasional receiver overruns that could occur. Previous to version 5.4, there would be an occasional dropped command response. Version 4.3 is identical to version 5.4 except for the change in bus speed.

Version 4.x fixed some bugs in the receive data engine. Previously, dropped receive data could occur.